

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 782 COMBINE</b>		
<b>Blower Motor</b> -Heavy Duty, 3/8" Double Shaft, 4 Wire, Ball Bearing Blower Wheel-LH Side, CCW Rotation Looking at Shaft End Blower Wheel-RH Side, CW Rotation Looking at Shaft End	117784C5	7231FHD
	539018R2	03045
	539077R2	03046
<b>Clutch Bearing</b> -Single Row Bearing, York, Tecumseh Double Row Bearing, York, Tecumseh	221438H1	10912
	221438H1	10909
<b>Clutch</b> -New Std. Duty Clutch, 7" Dia., 2 Groove, Standard Duty Single Row Bearing	143405C91	75R4502
<b>Compressor Conversion Kit</b> -York to Seltec	N/A	MD90357
<b>Compressor Shaft Seal Kit</b> -York, Standard Seal Kit	592263C91	20986
<b>Compressor</b> -New York, RH Suction Rotolock, Lo-Drum, P.I.N. 682 & Above	118250C91	7054
<b>Condenser</b> -High-Drum, P.I.N. 2125 & Above  Lo-Drum, P.I.N. 682 & Above	183901C1 165130C91	AC004422
	183901C1 165130C91	AC004422
<b>Evaporator</b> -Lo-Drum, P.I.N. 682 & Above, w/Bulb Type Expansion Valve & Flare Adapters Included for O'Ring & Flare Applications & Receiver Drier Mounted Near Condenser	118315C1 111468C2	EV904441
<b>Expansion Valve</b> -O'Ring	1280333C1	38877
<b>Receiver Drier</b> -O'Ring	118304C2	34305
<b>Switch</b> -Blower Low Pressure, Lo-Drum, P.I.N. 682 & Above High Pressure Thermostat	168822C2	71R1150
	111267C4	26503
	111266C1	26501
	109268C2	71R2300
<b>CASE/IH 1400 COMBINE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Motor w/Brackets 3/8" Double Shaft with 7/16" Stud Span Blower Wheel-LH Side, CCW Rotation Looking at Shaft End Blower Wheel-RH Side, CW Rotation Looking at Shaft End Resistor, 3 Terminal, Early Resistor, 4 Terminal	190333A1	04437
	142990C2	BM20051
	539018R2	03045
	539077R2	03046
	1255876C1	03242
	143169C1	03246
<b>Clutch Bearing</b> -Single Row Bearing, York, Tecumseh Double Row Bearing, York, Tecumseh	221438H1	10912
	221438H1	10909
<b>Clutch</b> -New Std. Duty Clutch, 7" Dia., 2 Groove, Standard Duty Single Row Bearing	143405C91	75R4502
<b>Compressor Conversion Kit</b> -York to Seltec	N/A	MD90357
<b>Compressor Shaft Seal Kit</b> -York, Standard Seal Kit	592263C91	20986
<b>Compressor</b> -New York, RH Suction Rotolock	118250C91	7054
<b>Condenser</b> -with O'Ring Fittings and Flare Adapters	183901C1 165130C91	AC004422
<b>Evaporator</b> -Includes 38872 Expansion Valve w/Flare Adapters and Receiver Drier is Mounted Near Condenser	118315C1 111468C2	EV904441
<b>Expansion Valve</b> -O'Ring	1280333C2	38877
<b>Heater Core</b>	539056R3	590-4445
<b>Receiver Drier</b> -O'Ring	118304C2	34305

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 1400 COMBINE Cont.</b>		
<b>Switch-Blower</b>	168822C2	71R1150
Low Pressure	11267C4	26503
High Pressure	111266C1	26501
Thermostat	109268C2	71R2300
<b>CASE/IH 1644 COMBINE</b>		
<b>Blower Motor-3/8" Double Shaft, 2 Wire Motor w/Brackets</b>	190333A1 142990C2	04437
3/8" Double Shaft with 7/16" Stud Span	142990C2	BM20051
Blower Wheel-LH Side, CCW Rotation Looking at Shaft End	539018R2	03045
Blower Wheel-RH Side, CW Rotation Looking at Shaft End	539077R2	03046
Resistor, 3 Terminal, Early	1255876C1	03242
Resistor, 4 Terminal	143169C1	03246
<b>Blower Motor-Blower Motor Assembly, High Efficiency Blower Update Kit For All Serial Numbers, Replaces Original Assembly On Combines with 4 or 2 Wire Motor, Applications with 2 Wire Motor Must Bypass Resistor and Wire Direct to Switch</b>	1255878C1	BA4022
<b>Clutch Bearing-Sanden SD508, 510</b>	A49663	52560
Sanden SD7H15	N/A	52565
<b>Clutch-New Sanden, 5.98" Dia., 2 Groove, Original R-12 Compressor</b>	83935C1	8298
New Sanden, 5.98" Dia., 2 Groove, Optional R134a Compressor	135324A2	8425AM
<b>Compressor Shaft Seal Kit-Sanden, Carbon Style</b>	A49665	52552
Sanden SD7H15, Lip Style	N/A	52554
<b>Compressor-New Sanden SD508, Original R-12 Compressor</b>	1977959C1 97204C1	9571AM
New Sanden SD7H15, Optional R134a Compressor	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Condenser</b>	84581C2	AC004415
<b>Evaporator-with Heater Core, Includes 71R8330 Expansion Valve</b>	1974632C3 135777C2	EV904447
<b>Expansion Valve-Block Type</b>	1990756C1	71R8330
<b>Receiver Drier-O'Ring</b>	143469C2	26825
<b>Switch-Blower</b>	168822C1	71R1150
Low Pressure	111267C4	26503
High Pressure	92038C1	26504
Thermostat	109268C2	71R2300

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 1666 COMBINE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Motor w/Brackets	190333A1 142990C2	04437
3/8" Double Shaft with 7/16" Stud Span	142990C2	BM20051
Blower Wheel, LH Side Counter Clockwise Rotation, Looking At Shaft End	539018R2	03045
Blower Wheel, RH Side Clockwise Rotation, Looking At Shaft End	539077R2	03046
Resistor, 3 Terminal	1255876C1	03242
Resistor, 4 Terminal	143169C1	03246
Blower Motor Assembly, High Efficiency Blower Update Kit For All Serial Numbers, Replaces Original Assembly On Combines with 4 or 2 Wire Motor, Applications with 2 Wire Motor Must Bypass Resistor and Wire Direct to Switch	1255878C1	BA4022
<b>Clutch Bearing</b> -Sanden SD508, 510	A49663	52560
Sanden SD7H15	N/A	52565
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove, Original R-12 Compressor	83935C1	8298
New Sanden, 5.98" Dia., 2 Groove, Optional R134a Compressor	135324A2	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	A49665	52552
<b>Compressor</b> -New Sanden SD508, Original R-12 Compressor	1977959C1 97204C1	9571AM
New Sanden SD7H15, Optional R134a Compressor	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Condenser</b>	84581C2	AC004415
<b>Evaporator</b> -with Heater Core, Includes 71R8330 Expansion Valve	1974632C3 135777C2	EV904447
<b>Expansion Valve</b> -Block Type	1990756C1	71R8330
<b>Receiver Drier</b> -O'Ring	143469C2	26825
<b>Switch</b> -Blower	168822C1	71R1150
Low Pressure	111267C4	26503
High Pressure	92038C1	26504
Thermostat	109268C2	71R2300
<b>CASE/IH 1688 COMBINE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Motor w/Brackets	190333A1 142990C2	04437
Blower Wheel, LH Side Counter Clockwise Rotation, Looking At Shaft End	539018R2	03045
Blower Wheel, RH Side Clockwise Rotation, Looking At Shaft End	539077R2	03046
Resistor, 3 Terminal, Early	1255876C1	03242
Resistor, 4 Terminal	143169C1	03246
<b>Clutch Bearing</b> -Sanden SD508, 510	A49663	52560
Sanden SD7H15	N/A	52565
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove, Original R-12 Compressor	83935C1	8298
New Sanden, 5.98" Dia., 2 Groove, Optional R134a Compressor	135324A2	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	A49665	52552

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 1688 COMBINE Cont.</b>		
<b>Compressor</b> -New Sanden SD508, Original R-12 Compressor	1977959C1 97204C1	9571AM
New Sanden SD7H15, Optional R134a Compressor	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Condenser</b>	84581C2	AC004415
<b>Evaporator</b> -with Heater Core, Includes 71R8330 Expansion Valve	1974632C3 135777C2	EV904447
<b>Expansion Valve</b> -Block Type	1990756C1	71R8330
<b>Receiver Drier</b> -O'Ring	143469C2	26825
<b>Switch</b> -Blower	168822C1	71R1150
Low Pressure	111267C4	26503
High Pressure	92038C1	26504
Thermostat	109268C2	71R2300
<b>CASE/IH 1800 COMBINE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Motor w/Brackets	190333A1	04437
3/8" Double Shaft with 7/16" Stud Span	142990C2	BM20051
Blower Wheel-LH Side, CCW Rotation Looking at Shaft End	539018R2	03045
Blower Wheel-RH Side, CW Rotation Looking at Shaft End	539077R2	03046
Resistor, 3 Terminal, Early	1255876C1	03242
Resistor, 4 Terminal	143169C1	03246
<b>Clutch Bearing</b> -Sanden SD508, 510	A49663	52560
Sanden SD7H15	N/A	52565
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove, Original R-12 Compressor	83935C1	8298
New Sanden, 5.98" Dia., 2 Groove, Optional R134a Compressor	135324A2	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	A49665	52552
<b>Compressor</b> -New Sanden SD508, Original R-12 Compressor	1977959C1 97204C1	9571AM
New Sanden SD7H15, Optional R134a Compressor	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Condenser</b> -with O'Ring Fittings and Flare Adapters	183901C1 165130C91	AC004422
<b>Evaporator</b> -with Heater Core, Includes 71R8330 Expansion Valve	1974632C3 135777C2	EV904447
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	1990758C2	26825
<b>Switch</b> -Blower	168822C2	71R1150
Low Pressure	111267C4	26503
High Pressure	92038C1	26504
Thermostat	109268C2	71R2300

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 1822 COMBINE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Motor w/Brackets 3/8" Double Shaft with 7/16" Stud Span Blower Wheel-LH Side, CCW Rotation Looking at Shaft End Blower Wheel-RH Side, CW Rotation Looking at Shaft End Resistor, 3 Terminal Resistor, 4 Terminal Blower Motor Assembly, High Efficiency Blower Update Kit For All Serial Numbers, Replaces Original Assembly On Combines with 4 or 2 Wire Motor, Applications with 2 Wire Motor Must Bypass Resistor and Wire Direct to Switch	142990C2	04437
	142990C2	BM20051
	539018R2	03045
	539077R2	03046
	1255876C1	03242
	143169C1	03246
	1255878C1	BA4022
<b>Clutch Bearing</b> -Single Row Bearing Double Row Bearing Sanden SD508, 510 Sanden SD7H15	221438H1	10912
	221438H1	10909
	A49663	52560
	N/A	52565
<b>Clutch</b> -New Std. Duty Clutch, 7" Dia., 2 Groove, Standard Duty Single Row Bearing New Sanden, 5.98" Dia., 2 Groove, Serial No. JJC00126 & Above, Original R-12 Compressor New Sanden, 5.98" Dia., 2 Groove, Serial No. JJC00126 & Above, Optional R134a Compressor	143405C91	75R4502
	83935C1	8298
	135324A2	8425AM
<b>Compressor Conversion Kit</b> -York to Sanden	N/A	MD90345
<b>Compressor Shaft Seal Kit</b> -York, Standard Seal Kit Sanden, Carbon Style	592263C91	20986
	A49665	52552
<b>Compressor</b> -New York, RH Tube O New Sanden SD508, Serial No. JJC00126 & Above, Original R-12 Compressor New Sanden SD7H15, Serial No. JJC00126 & Above, Optional R134a Compressor New Aftermarket Compressor Replaces 4609	1255750C91	7040
	1977959C1	9571AM
	1999755C2/C3	4609
	--	4609AM
<b>Condenser</b> -with O'Ring Fittings and Flare Adapters	183901C1 165130C91	AC004422
<b>Evaporator</b> -with Heater Core, Includes 71R8330 Expansion Valve	135777C2 79675C92	EV904447
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	143469C2	26825
<b>Switch</b> -Blower Low Pressure High Pressure High Pressure, Serial No. JJC0012691 & Above Blower Motor Relay Thermostat	168822C2	71R1150
	111267C4	26503
	111266C1	26501
	92038C1	26504
	73161287 1983394C1	71R1722
	109268C2	71R2300

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 1844 COMBINE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Motor w/Brackets 3/8" Double Shaft with 7/16" Stud Span Blower Wheel-LH Side, CCW Rotation Looking at Shaft End Blower Wheel-RH Side, CW Rotation Looking at Shaft End Resistor, 3 Terminal Resistor, 4 Terminal Blower Motor Assembly, High Efficiency Blower Update Kit For All Serial Numbers, Replaces Original Assembly On Combines with 4 or 2 Wire Motor, Applications with 2 Wire Motor Must Bypass Resistor and Wire Direct to Switch	142990C2	04437
	142990C2	BM20051
	539018R2	03045
	539077R2	03046
	1255876C1	03242
	143169C1	03246
	1255878C1	BA4022
<b>Clutch Bearing</b> -Single Row Bearing Double Row Bearing Sanden SD508, 510 Sanden SD7H15	221438H1	10912
	221438H1	10909
	A49663	52560
	N/A	52565
<b>Clutch</b> -New Std. Duty Clutch, 7" Dia., 2 Groove, Standard Duty Single Row Bearing New Sanden, 5.98" Dia., 2 Groove, Original R-12 Compressor New Sanden, 5.98" Dia., 2 Groove, Optional R134a Compressor	143405C91	75R4502
	83935C1	8298
	135324A2	8425AM
<b>Compressor Shaft Seal Kit</b> -York, Standard Seal Kit Sanden, Carbon Style	592263C91	20986
	A49665	52552
<b>Compressor</b> -New York, RH Suction Tube O, Serial No. JJC002461 & Below New Sanden SD508, Original R-12 Compressor  New Sanden SD7H15, Optional R134a Compressor New Aftermarket Compressor Replaces 4609	1255750C91	7040
	1977959C1 97204C1	9571AM
	1999755C2/C3	4609
	--	4609AM
<b>Condenser</b> -with O'Ring Fittings and Flare Adapters	183901C1 165130C91	AC004422
	135777C2 79675C92	EV904447
<b>Evaporator</b> -with Heater Core, Includes 71R8330 Expansion Valve	1990756C2 98370C3	71R8330
<b>Expansion Valve</b> -Block Type	143469C2	26825
<b>Receiver Drier</b> -O'Ring	168822C2	71R1150
<b>Switch</b> -Blower Low Pressure High Pressure High Pressure Blower Motor Relay  Thermostat	111267C4	26503
	111266C1	26501
	92038C1	26504
	73161287 1983394C1	71R1722
	109268C2	71R2300

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 2022 COMBINE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Motor with Brackets 3/8" Double Shaft with 7/16" Stud Span Blower Wheel-LH Side, CCW Rotation Looking at Shaft End Blower Wheel-RH Side, CW Rotation Looking at Shaft End Resistor, 3 Terminal Resistor, 4 Terminal Blower Motor Assembly, High Efficiency Blower Update Kit For All Serial Numbers, Replaces Original Assembly On Combines with 4 or 2 Wire Motor, Applications with 2 Wire Motor Must Bypass Resistor and Wire Direct to Switch	190333A1	04437
	142990C2	BM20051
	539018R2	03045
	539077R2	03046
	1255876C1	03242
	143169C1	03246
	1255878C1	BA4022
<b>Clutch Bearing</b> -Sanden SD7H15 Sanden SD508, 510	N/A	52565
	A49663	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove, Original R-12 Compressor New Sanden SD7H15, 5.98" Dia., 2 Groove	83935C1	8298
	135324A1/A2	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style Sanden, Lip Type	A49665	52552
	N/A	52554
<b>Compressor</b> -New Sanden SD508, Original R-12 Compressor  New Sanden SD7H15, R134a Compressor New Aftermarket Compressor Replaces 4609	1977959C1 97204C1	9571AM
	1999755C2/C3	4609
	--	4609AM
<b>Condenser</b> -with O'Ring Fittings and Flare Adapters	183901C1 165130C91	AC004422
<b>Evaporator</b> -with Heater Core, Includes 71R8330 Expansion Valve	1974632C3 135777C2	EV904447
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	1990758C2	26825
<b>Switch</b> -Blower Low Pressure High Pressure High Pressure Thermostat	168822C2	71R1150
	111267C4	26503
	92038C1	26504
	1999925C1	26512
	109268C2	71R2300
<b>CASE/IH 2044 COMBINE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Motor with Brackets 3/8" Double Shaft with 7/16" Stud Span Blower Wheel-LH Side, CCW Rotation Looking at Shaft End Blower Wheel-RH Side, CW Rotation Looking at Shaft End Resistor, 3 Terminal Resistor, 4 Terminal Blower Motor Assembly, High Efficiency Blower Update Kit For All Serial Numbers, Replaces Original Assembly On Combines with 4 or 2 Wire Motor, Applications with 2 Wire Motor Must Bypass Resistor and Wire Direct to Switch	190333A1	04437
	142990C2	BM20051
	539018R2	03045
	539077R2	03046
	1255876C1	03242
	143169C1	03246
	1255878C1	BA4022
<b>Clutch Bearing</b> -Sanden SD7H15 Sanden SD508, 510	N/A	52565
	A49663	52560

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 2044 COMBINE Cont.</b>		
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove, Original R-12 Compressor New Sanden SD7H15, 5.98" Dia., 2 Groove, R-134a Compressor	83935C1	8298
	135324A1/A2	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style Sanden, Lip Type	A49665	52552
	N/A	52554
<b>Compressor</b> -New Sanden SD508, Original R-12 Compressor  New Sanden SD7H15, R134a Compressor New Aftermarket Compressor Replaces 4609	1977959C1 97204C1	9571AM
	1999755C2/C3	4609
	--	4609AM
<b>Condenser</b> -with O'Ring Fittings and Flare Adapters	183901C1 165130C91	AC004422
<b>Evaporator</b> -with Heater Core, Includes 71R8330 Expansion Valve	1974632C3 135777C2	EV904447
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	1990758C2	26825
<b>Switch</b> -Blower  Low Pressure High Pressure High Pressure Thermostat	168822C2	71R1150
	111267C4	26503
	92038C1	26504
	1999925C1	26512
	109268C2	71R2300
<b>CASE/IH 2055 COMBINE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Motor w/Brackets 3/8" Double Shaft with 7/16" Stud Span Blower Wheel-LH Side, CCW Rotation Looking at Shaft End Blower Wheel-RH Side, CW Rotation Looking at Shaft End Resistor, 3 Terminal Resistor, 4 Terminal  Blower Motor Assembly, High Efficiency Blower Update Kit For All Serial Numbers, Replaces Original Assembly On Combines with 4 or 2 Wire Motor, Applications with 2 Wire Motor Must Bypass Resistor and Wire Direct to Switch	142990C2	04437
	142990C2	BM20051
	539018R2	03045
	539077R2	03046
	1255876C1	03242
	143169C1	03246
	1255878C1	BA4022
<b>Clutch Bearing</b> -Sanden SD508, 510 Sanden SD7H15	A49663	52560
	N/A	52565
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove, Original R-12 Compressor New Sanden, 5.98" Dia., 2 Groove, Optional R134a Compressor	83935C1	8298
	135324A2	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden SD508, 510, Carbon Style, Original R-12 Compressor Sanden SD7H15, Lip Style, Optional R134a Compressor	A49665	52552
	N/A	52554
<b>Compressor</b> -New Sanden SD508, Original R-12 Compressor  New Sanden SD7H15, Optional R134a Compressor New Aftermarket Compressor Replaces 4609	1977959C1 97204C1	9571AM
	1999755C2/C3	4609
	--	4609AM
<b>Condenser</b>	84581C1	AC004415
<b>Evaporator</b> -with Heater Core, Includes 71R8330 Expansion Valve	1974632C3 135777C2	EV904447



<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 2055 COMBINE Cont.</b>		
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	1990758C2	26825
<b>Switch</b> -Blower	168822C2	71R1150
Low Pressure	111267C4	26503
High Pressure	92038C1	26504
Blower Motor Relay	73161287 1983394C1	71R1722
Thermostat	109268C2	71R2300
<b>CASE/IH 2144 COMBINE</b>		
<b>Blower Motor</b> -Assembly without Resistor	1977564C2	BA4020
Resistor, Serial No. JAB0100387 & Below	1255876C1	03242
Resistor, Serial No. JAB0100387 & Above	1343938C2	03241
Wiring Harness, Use with 03241 Resistor	N/A	WH10090
Aftermarket Blower Assembly with Resistor	1977564C2	BA40201
Blower Motor Assembly For All Serial Number's, Includes Early & Late Style Wiring Harness	--	BA40201K
<b>Clutch Bearing</b> -Sanden SD7H15	N/A	52565
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	135324A1	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Lip Type	N/A	52554
<b>Compressor</b> -New Sanden SD7H15	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Condenser</b>	84581C2	AC004415
<b>Evaporator</b>	121590A2	EV904450
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	1990758C2	26825
<b>Switch</b> -Blower	N/A	N/A
Low Pressure	122579A1	26502
High Pressure	1999925C1	26512
Thermostat	N/A	N/A
<b>CASE/IH 2155 COMBINE</b>		
<b>Blower Motor</b> -Assembly without Resistor	1977564C2	BA4020
Resistor, Serial No. JAB0100387 & Below	1255876C1	03242
Resistor, Serial No. JAB0100387 & Above	1343938C2	03241
Wiring Harness, Use with 03241 Resistor	N/A	WH10090
Aftermarket Blower Assembly with Resistor	1977564C2	BA40201
Blower Motor Assembly For All Serial Number's, Includes Early & Late Style Wiring Harness	--	BA40201K
<b>Clutch Bearing</b> -Sanden, SD7H15	N/A	52565
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	135324A1	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Lip Type	N/A	52554
<b>Compressor</b> -New Sanden SD7H15	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Condenser</b>	84581C2	AC004415

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 2155 COMBINE Cont.</b>		
Evaporator-with Heater Core	121590A2/A3	EV904450
Expansion Valve-Block Type	1990756C2 98370C3	71R8330
Receiver Drier-O'Ring	1990758C2	26825
Switch-Low Pressure	122579A1	26502
High Pressure	1999925C1	26512
<b>CASE/IH 2166 COMBINE</b>		
Blower Motor-Assembly without Resistor	1977564C2	BA4020
Resistor, Serial No. JAB0100387 & Below	1255876C1	03242
Resistor, Serial No. JAB0100387 & Above	1343938C2	03241
Wiring Harness, Use with 03241 Resistor	N/A	WH10090
Aftermarket Blower Assembly with Resistor	1977564C2	BA40201
Blower Motor Assembly For All Serial Number's, Includes Early & Late Style Wiring Harness	--	BA40201K
Clutch Bearing-Sanden SD7H15	N/A	52565
Clutch-New Sanden, 5.98" Dia., 2 Groove	135324A1	8425AM
Compressor Shaft Seal Kit-Sanden, Lip Type	N/A	52554
Compressor-New Sanden SD7H15	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
Condenser	84581C2	AC004415
Evaporator	121590A2/A3	EV904450
Expansion Valve-Block Type	1990756C2 98370C3	71R8330
Receiver Drier-O'Ring	1990758C2	26825
Switch-Low Pressure	122579A1	26502
High Pressure	1999925C1	26512
<b>CASE/IH 2188 COMBINE</b>		
Blower Motor-Assembly without Resistor	1977564C2	BA4020
Resistor, Serial No. JAB0100387 & Below	1255876C1	03242
Resistor, Serial No. JAB0100387 & Above	1343938C2	03241
Wiring Harness, Use with 03241 Resistor	N/A	WH10090
Aftermarket Blower Assembly with Resistor	1977564C2	BA40201
Blower Motor Assembly For All Serial Number's, Includes Early & Late Style Wiring Harness	--	BA40201K
Clutch Bearing-Sanden, For SD7H15 Compressor Only	N/A	52565
Clutch-New Sanden, 5.98" Dia., 2 Groove	135324A1	8425AM
Compressor Shaft Seal Kit-Sanden, Lip Type	N/A	52554
Compressor-New Sanden SD7H15	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
Condenser	84581C2	AC004415
Evaporator	121590A2/A3	EV904450
Expansion Valve-Block Type	1990756C2 98370C3	71R8330
Receiver Drier-O'Ring	1990758C2	26825

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 2188 COMBINE Cont.</b>		
<b>Switch</b> -Low Pressure	122579A1	26502
High Pressure	1999925C1	26512
<b>CASE/IH 2344 COMBINE</b>		
<b>Blower Motor</b> -Assembly without Resistor	1977564C2	BA4020
Resistor, Serial No. JAB0100387 & Below	1255876C1	03242
Resistor, Serial No. JAB0100387 & Above	1343938C2	03241
Wiring Harness, Use with 03241 Resistor	N/A	WH10090
Aftermarket Blower Assembly with Resistor	1977564C2	BA40201
HD Blower Assembly with OEM Wire Harness, SN JJC0252950 & Above	323610A1 84222524	BA4019
Aftermarket Blower Assembly, SN JJC0252950 & Above	323610A1 84222524	BA40191
Blower Motor Assembly For All Serial Number's, Includes Early & Late Style Wiring Harness	--	BA40201K
<b>Clutch Bearing</b> -Sanden SD7H15	N/A	52565
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	135324A1	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Lip Type	N/A	52554
<b>Compressor</b> -New Sanden SD7H15	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Condenser</b>	84581C2	AC004415
<b>Evaporator</b>	121590A2/A3	EV904450
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	1990758C2	26825
<b>Switch</b> -Low Pressure	122579A1	26502
High Pressure	232948A1	26512
<b>CASE/IH 2366 COMBINE</b>		
<b>Blower Motor</b> -Assembly without Resistor	1977564C2	BA4020
Resistor, Serial No. JAB0100387 & Below	1255876C1	03242
Resistor, Serial No. JAB0100387 & Above	1343938C2	03241
Wiring Harness, Use with 03241 Resistor	N/A	WH10090
Aftermarket Blower Assembly with Resistor	1977564C2	BA40201
Assembly, Serial No. JJC0252950 and Above	323610A1 84222524	BA4019
Aftermarket Blower Assembly, SN JJC0252950 & Above	323610A1 84222524	BA40191
Blower Motor Assembly For All Serial Number's, Includes Early & Late Style Wiring Harness	--	BA40201K
<b>Clutch Bearing</b> -Sanden SD7H15	N/A	52565
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	135324A1	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Lip Type	N/A	52554
<b>Compressor</b> -New Sanden SD7H15	1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Condenser</b>	84581C2	AC004415

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 2366 COMBINE Cont.</b>		
<b>Evaporator</b> -Serial No. JJC025249 & Below Serial No. JJC0252950 & Above	121590A2/A3	EV904450
	377560A1	EV904451
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	1990758C2	26825
<b>Switch</b> -Low Pressure, Serial No. JJC0252949 & Below Low Pressure, Serial No. JJC0252950 and above High Pressure, Serial No. JJC0252949 & Below High Pressure, Serial No. JJC0252950 & Above	122579A1	26502
	284272A1, 2, 3	26520
	232948A1	26512
	284273A1/A2 87000227	26519
<b>CASE/IH 2377 COMBINE</b>		
<b>Blower Motor</b> -Assembly Aftermarket Blower Assembly  Blower Motor Assembly, Pressurizer	323610A1	BA4019
	323610A1 84222524	BA40191
	87107380 330137A1	BA3940
<b>Clutch Bearing</b> -Sanden SD7H15	N/A	52565
<b>Clutch</b> -New Sanden	135324A2	8425AM
<b>Compressor</b> -New Sanden SD7H15HD New Aftermarket Compressor Replaces 4609	86993462	4609
	--	4609AM
<b>Condenser</b>	275094A3	AC002027
<b>Evaporator</b>	877560A1	N/A
<b>Expansion Valve</b> -Block Type	386535A1	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Low Pressure High Pressure	284272A1/,2, 3	26520
	369798A2	N/A
<b>CASE/IH 2388 COMBINE</b>		
<b>Blower Motor</b> -Assembly without Resistor Resistor, Serial No. JAB0100387 & Below Resistor, Serial No. JAB0100387 & Above Wiring Harness, Use with 03241 Resistor Blower Assembly, Serial No. JJC0267150 and Above  Aftermarket Blower Assembly  Aftermarket Blower Assembly with Resistor Blower Motor Assembly For All Serial Number's, Includes Early & Late Style Wiring Harness Blower Motor Assembly, Pressurizer	1977564C2	BA4020
	1255876C1	03242
	1343938C2	03241
	N/A	WH10090
	323610A1 84222524	BA4019
	323610A1 84222524	BA40191
	1977564C2	BA40201
	--	BA40201K
	87107380 330137A1	BA3940
	N/A	52565
<b>Clutch Bearing</b> -Sanden SD7H15	N/A	52565
<b>Clutch</b> -New Sanden Clutch, 5.98" Dia., 2 Groove	135324A1	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Lip Type	N/A	52554
<b>Compressor</b> -New Sanden SD7H15 New Aftermarket Compressor Replaces 4609	1999755C2/C3	4609
	--	4609AM
<b>Condenser</b>	275094A3	AC002027

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 2388 COMBINE Cont.</b>		
<b>Evaporator</b> -Serial No. JJC025249 & Below Serial No. JJC0252950 & Above	121590A3, A2	EV904450
	377560A1	EV904451
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	1990758C2	26825
<b>Switch</b> -Low Pressure, Serial No. JJC0252949 & Below Low Pressure, Serial No. JJC0252950 and Above High Pressure, Serial No. JJC0252949 & Below High Pressure, Serial No. JJC0252950 and Above	122579A1	26502
	284272A1, 2, 3	26520
	232948A1	26512
	284273A1, 2, 3	26519
<b>CASE/IH 2555 COMBINE</b>		
<b>Blower Motor</b> -Assembly without Resistor Resistor, Serial No. JAB0100387 & Below Resistor, Serial No. JAB0100387 & Above Wiring Harness, Use with 03241 Resistor Aftermarket Blower Assembly with Resistor Blower Motor Assembly For All Serial Number's, Includes Early & Late Style Wiring Harness	1977564C2	BA4020
	1255876C1	03242
	1343938C2	03241
	N/A	WH10090
	1977564C2	BA40201
	--	BA40201K
<b>Clutch Bearing</b> -Sanden SD7H15	N/A	52565
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	135324A1	8425AM
<b>Compressor Shaft Seal Kit</b> -Sanden, Lip Type	N/A	52554
<b>Compressor</b> -New Sanden SD7H15 New Aftermarket Compressor Replaces 4609	1999755C2/C3	4609
	--	4609AM
<b>Condenser</b>	84581C2	AC004415
<b>Evaporator</b> -with Heater Core	121590A2/A3	EV904450
<b>Expansion Valve</b> -Block Type	1990756C2 98370C3	71R8330
<b>Receiver Drier</b> -O'Ring	1990758C2	26825
<b>Switch</b> -Low Pressure High Pressure	122579A1	26502
	1999925C1	26512
<b>CASE/IH 2577 COMBINE</b>		
<b>Blower Motor</b> -Assembly Aftermarket Blower Assembly Blower Motor Assembly, Pressurizer	323610A1	BA4019
	323610A1 84222524	BA40191
	87107380 330137A1	BA3940
<b>Compressor</b> -New Sanden SD7H15 New Aftermarket Compressor Replaces 4609	86993462 1999755C2/C3	4609
	--	4609AM
<b>Condenser</b>	444922A3	N/A
<b>Evaporator</b>	377560A1	N/A
<b>Expansion Valve</b> -Block Type	386535A1	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Low Pressure High Pressure	87323829	26530
	369798A2	N/A

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 2588 COMBINE</b>		
<b>Blower Motor-Assembly</b>	323610A1	BA4019
Aftermarket Blower Assembly	323610A1 84222524	BA40191
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
<b>Compressor-New Sanden SD7H15</b>	86993462 1999755C2/C3	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Condenser</b>	444922A3	N/A
<b>Evaporator</b>	377560A1	EV904451
<b>Expansion Valve-Block Type</b>	386535A1	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch-Low Pressure</b>	87323829	26530
High Pressure	369798A2	N/A
<b>CASE/IH 5088 COMBINE</b>		
<b>Blower Motor-Assembly</b>	323610A1	BA4019
Aftermarket Blower Assembly	323610A1 84222524	BA40191
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
<b>Clutch-New Sanden, 5.98" Dia., 2 Groove</b>	135324A2	8425AM
<b>Compressor-New Sanden SD7H15</b>	86993462	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Evaporator-With Heater Core</b>	377560A1	EV904451
<b>Expansion Valve-Block Type</b>	386535A1	71R8330
<b>Receiver Drier-O'Ring</b>	1990758C2	26825
<b>Switch-Low Pressure</b>	87323829	26530
<b>CASE/IH 6088 COMBINE</b>		
<b>Blower Motor-Assembly</b>	323610A1	BA4019
Aftermarket Blower Assembly	323610A1 84222524	BA40191
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
<b>Clutch-New Sanden, 5.98" Dia., 2 Groove</b>	135324A2	8425AM
<b>Compressor-New Sanden SD7H15</b>	86993462	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Evaporator-with Heater Core</b>	377560A1	EV904451
<b>Expansion Valve-Block Type</b>	386535A1	71R8330
<b>Receiver Drier-O'Ring</b>	1990758C2	26825
<b>Switch-Low Pressure</b>	87323829	26530

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 7010 COMBINE</b>		
<b>Blower Motor-Assembly</b>	87663947	BA4045
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
<b>Clutch-New Sanden</b>	403585A1	600-9851
<b>Compressor-New Sanden SD7H15HD</b>	86993463	4768
New Compressor (Aftermarket) Replacement for 4768	--	4768AM
<b>Condenser</b>	87389077	N/A
<b>Evaporator</b>	87355949	EV904457
<b>Expansion Valve-Block Type</b>	87033212	71R8330
<b>Receiver Drier</b>	87105840	21723
	87280717	N/A
<b>Switch-Low Pressure</b>	87000228	26520
High Pressure	87000227	26519
Electronic Temperature	84800780	26602
Air Temperature Sensor	86531126	26600
Air Temperature Sensor Probe	86531133	26601
<b>CASE/IH 7088 COMBINE</b>		
<b>Blower Motor-Assembly</b>	323610A1	BA4019
Aftermarket Blower Assembly	323610A1 84222524	BA40191
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
<b>Clutch-New Sanden, 5.98" Dia., 2 Groove</b>	135324A2	8425AM
<b>Compressor-New Sanden SD7H15</b>	86993462	4609
New Aftermarket Compressor Replaces 4609	--	4609AM
<b>Evaporator-with Heater Core</b>	377560A1	EV904451
<b>Expansion Valve-Block Type</b>	386535A1	71R8330
<b>Receiver Drier-O'Ring</b>	1990758C2	26825
<b>Switch-Low Pressure</b>	87323829	26530
<b>CASE/IH 7120 COMBINE</b>		
<b>Blower Motor-Assembly</b>	87663947	BA4045
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
<b>Clutch-New Sanden</b>	403585A1	600-9851
<b>Compressor-New Sanden SD7H15</b>	86993463	4768
New Compressor (Aftermarket) Replacement for 4768	--	4768AM
<b>Evaporator</b>	87754243	EV904459
<b>Expansion Valve-Block Type</b>	82023542	EX03738

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 7120 COMBINE Cont.</b>		
Receiver Drier-In Line, O'Ring	295006A1 87105840	21723
Switch-Low Pressure	87323829	26530
High Pressure	87000227	26519
<b>CASE/IH 8010 COMBINE</b>		
Blower Motor-Assembly	87663947	BA4045
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
Clutch-New Sanden	403585A1	600-9851
Compressor-New Sanden SD7H15HD	86993463	4768
New Compressor (Aftermarket) Replacement for 4768	--	4768AM
Condenser	87284217	N/A
Evaporator	87355949	EV904457
Expansion Valve-Block Type	87033212	71R8330
Receiver Drier	87105840	21723
Switch-Low Pressure	82000228	26520
High Pressure	82000227	26519
Electronic Temperature	84800780	26602
Air Temperature Sensor	86531126	26600
Air Temperature Sensor Probe	86531133	26601
<b>CASE/IH AFX8010 COMBINE</b>		
Blower Motor-Assembly	84431351	73R5622
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
Clutch-New Sanden	403585A1	600-9851
Compressor-New Sanden SD7H15HD	86993463	4768
New Compressor (Aftermarket) Replacement for 4768	--	4768AM
Condenser	87284217	N/A
Evaporator	86523242	N/A
Serial No. HAJ106401 & Above	87355949	EV904457
Expansion Valve-Block Type	84015397 87033212	71R8330
Receiver Drier	87105840	21723



<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH AFX8010 COMBINE Cont.</b>		
Switch-Low Pressure	284272A1/A2/ A3 87000228	26520
High Pressure	284273A1/A2/ A3 87000227	26600
Air Temperature Sensor	86531126	26600
Air Temperature Sensor Probe	86531133	26601
Thermostat, Preset	84078518	71R3200
<b>CASE/IH 8120 COMBINE</b>		
Blower Motor-Assembly	87663947	BA4045
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
Clutch-New Sanden	403585A1	600-9851
Compressor-New Sanden SD7H15	86993463	4768
New Compressor (Aftermarket) Replacement for 4768	--	4768AM
Evaporator	87754243	EV904459
Expansion Valve-Block Type	82023542	EX03738
Receiver Drier-In Line, O'Ring	295006A1 87105840	21723
Switch-Low Pressure	87323829	26530
High Pressure	87000227	26519
<b>CASE/IH 9010 COMBINE</b>		
Blower Motor-Assembly	87663947	BA4045
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
Clutch-New Sanden	403585A1	600-9851
Compressor-New Sanden SD7H15HD	86993463	4768
New Compressor (Aftermarket) Replacement for 4768	--	4768AM
Condenser	87284217	N/A
Evaporator	87355949	EV904457
Expansion Valve-Block Type	87033212	71R8330
Receiver Drier	87105840	21723
Switch-Low Pressure	82000228	26520
High Pressure	82000227	26519
Electronic Temperature	84800780	26602
Air Temperature Sensor	86531126	26600
Air Temperature Sensor Probe	86531133	26601

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH 9120 COMBINE</b>		
<b>Blower Motor-Assembly</b>	87663947	BA4045
Blower Motor Assembly, Pressurizer	87107380 330137A1	BA3940
<b>Clutch-New Sanden</b>	403585A1	600-9851
<b>Compressor-New Sanden SD7H15</b>	86993463	4768
New Compressor (Aftermarket) Replacement for 4768	--	4768AM
<b>Evaporator</b>	87754243	EV904459
<b>Expansion Valve-Block Type</b>	82023542	EX03738
<b>Receiver Drier</b>	87105840	21723
<b>Switch-Low Pressure</b>	87323829	26530
High Pressure	87000227	26519
<b>CASE/IH CT5050 COMBINE</b>		
<b>Blower Motor-Assembly</b>	89512492 9512492	BA4016
<b>Compressor-New Sanden SD7H13</b>	84039022	CO093998
<b>Expansion Valve-Block Type</b>	84015397 87033212	71R8330
<b>Receiver Drier</b>	696524 89832539	74R3536
<b>Switch-Low Pressure</b>	84012146 87366055 03247424	26539
High Pressure	84012145 87366056 03247432	26540
<b>CASE/IH CT5060 COMBINE</b>		
<b>Blower Motor-Assembly</b>	89512492 9512492	BA4016
<b>Compressor-New Sanden SD7H13</b>	84039022	CO093998
<b>Expansion Valve-Block Type</b>	84015397 87033212	71R8330
<b>Receiver Drier</b>	696524 89832539	74R3536
<b>Switch-Low Pressure</b>	84012146 87366055 03247424	26539
High Pressure	84012145 87366056 03247432	26540
<b>CASE/IH CT5070 COMBINE</b>		
<b>Blower Motor-Assembly</b>	89512492 9512492	BA4016
<b>Compressor-New Sanden SD7H13</b>	84039022	CO093998
<b>Expansion Valve-Block Type</b>	84015397 87033212	71R8330

<b>CASE/IH COMBINE</b>	<b>OEM</b>	<b>PART #</b>
<b>CASE/IH CT5070 COMBINE Cont.</b>		
<b>Receiver Drier</b>	696524 89832539	74R3536
<b>Switch</b> -Low Pressure	84012146 87366055 03247424	26539
High Pressure	84012145 87366056 03247432	26540
<b>CASE/IH CT5080 COMBINE</b>		
<b>Blower Motor</b> -Assembly	89512492 9512492	BA4016
<b>Compressor</b> -New Sanden SD7H13	84039022	CO093998
<b>Expansion Valve</b> -Block Type	84015397 87033212	71R8330
<b>Receiver Drier</b>	696524 89832539	74R3536
<b>Switch</b> -Low Pressure	84012146 87366055 03247424	26539
High Pressure	84012145 87366056 03247432	26540