

MACDON	OEM	PART #
MACDON 7000 SWATHER		
Compressor-New Sanden SD510, R-12 System	N/A	9103AM
Expansion Valve-Flare	109710	71R8080
Receiver Drier-(May Require 2 461-2525 Fittings)	N/A	74R2706
MACDON 9000 SWATHER		
Blower Motor-Double Shaft	PM736	BM20035
Compressor-New Sanden SD7H15	N/A	4664
Expansion Valve-Block Type	42879	38620
Receiver Drier	44192	26836
MACDON 9250 SWATHER		
Compressor-New Sanden SD7H15	42920	4664
Expansion Valve-Block Type	42879	38620
Receiver Drier	112082	74R2607
MACDON 9300 SWATHER		
Compressor-New Sanden SD7H15	N/A	4664
Expansion Valve-Block Type	42879	38620
Receiver Drier	44517	74R2607
MACDON 9350 SWATHER		
Compressor-New Sanden SD7H15	42920	4664
Expansion Valve-Block Type	42879	38620
Receiver Drier	112082	74R2607
MACDON 9352 SWATHER		
Compressor-New Sanden SD7H15	42920	4664
Expansion Valve-Block Type	42879	38620
Receiver Drier	112082	74R2607
MACDON 9352C SWATHER		
Compressor-New Sanden SD7H15	42920	4664
Expansion Valve-Block Type	42879	38620
Receiver Drier	112082	74R2607
MACDON 9352I SWATHER		
Compressor-New Sanden SD7H15	42920	4664
Expansion Valve-Block Type	42879	38620
Receiver Drier	112082	74R2607
NEWER MACDON SWATHERS		
Blower Motor	PM736 / PM736X	BM20035