

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ AGROPLUS 60</b>		
Compressor-New Sanden SD7H15	01103234	CO09612
Receiver Drier-In Line, O'Ring	N/A	RD03395
<b>DEUTZ AGROPLUS 70</b>		
Compressor-New Sanden SD7H15	01103234	CO09612
Receiver Drier-In Line, O'Ring	N/A	RD03395
<b>DEUTZ AGROPLUS 75</b>		
Compressor-New Sanden SD7H15	01103234	CO09612
Receiver Drier-In Line, O'Ring	N/A	RD03395
<b>DEUTZ AGROPLUS 80</b>		
Compressor-New Sanden SD7H15	01103234	CO09612
Receiver Drier-In Line, O'Ring	N/A	RD03395
<b>DEUTZ AGROPLUS 85</b>		
Compressor-New Sanden SD7H15	01103234	CO09612
Receiver Drier-In Line, O'Ring	N/A	RD03395
<b>DEUTZ AGROPLUS 95</b>		
Compressor-New Sanden SD7H15	01103234	CO09612
Receiver Drier-In Line, O'Ring	N/A	RD03395
<b>DEUTZ AGROPLUS 100</b>		
Compressor-New Sanden SD7H15	01103234	CO09612
Receiver Drier-In Line, O'Ring	N/A	RD03395
<b>DEUTZ D6507C TRACTOR</b>		
<b>Blower Motor</b> -5/16" Double Shaft, 4 Wire	4317577 4339305	BA4070
Replacement Motor For BA4070	N/A	BM4071
Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW	N/A	BW270
Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW	N/A	BW271
Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897	52552
<b>Compressor</b> -New Sanden SD508	4338042 7807944	8387
<b>Condenser</b>	4341371	AC001009
<b>Evaporator</b>	4347538 4402838	N/A
<b>Expansion Valve</b> -Block Type	N/A	EX03700
<b>Receiver Drier</b> -O'Ring, Replaces Early Style RD03349, Requires Some Modification	4346256 4353731 70276903	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ D6507C TRACTOR Cont.</b>		
<b>Switch-Blower</b>	4322169 4372360	71R1210
Pressure, Drier Mount	4337855	71R7500
Thermostat	4338212 4360486	26301
<b>DEUTZ D7007C TRACTOR</b>		
<b>Blower Motor</b> -5/16" Double Shaft, 4 Wire	4317577 4339305	BA4070
Replacement Motor For BA4070	N/A	BM4071
Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW	N/A	BW270
Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW	N/A	BW271
Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897	52552
<b>Compressor</b> -New Sanden SD508	4338042 7807944	8387
<b>Condenser</b>	4341371	AC001009
<b>Evaporator</b>	4347538 4402838	N/A
<b>Expansion Valve</b> -Block Type	N/A	EV03700
<b>Receiver Drier</b> -O'Ring, Replaces Early Style RD03349, Requires Some Modification	4346256 4353731 70276903	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349
<b>Switch-Blower</b>	4322169 4372360	71R1210
Pressure, Drier Mount	4337855	71R7500
Thermostat	4338212 4360486	26301
<b>DEUTZ D7807C TRACTOR</b>		
<b>Blower Motor</b> -5/16" Double Shaft (Must Use Original Wheels) Dash Mount	4317577 4339305	BA4070
Replacement Motor For BA4070	N/A	BM4071
Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW	N/A	BW270
Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW	N/A	BW271
Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897	52552

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ D7807C TRACTOR Cont.</b>		
Compressor-New Sanden SD508	4338042 7807944	8387
Condenser	4341371	AC001009
Evaporator	4347538 4402838	N/A
Expansion Valve-Block Type	N/A	EX03700
Receiver Drier-O'Ring, Replaces Early Style RD03349, Requires Some Modification	4346256 4353731 70276903	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349
Switch-Thermostat	4338212 4360486	26301
Blower	4322169 4372360	71R1210
Pressure, Drier Mount	4337855	71R7500
<b>DEUTZ DX3.10 TRACTOR</b>		
Blower Motor-Condenser Motor, 11" Universal Electric Fan Assembly Condenser Fan, with Relay and Wiring Harness Blower Motor	4322172	FA11235
	4322172	FA11235-1
	4348005	BA4080
Clutch Bearing-Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
Clutch-New Sanden, 5.98" Dia., 2 Groove New Clutch Coil, Sanden	4327654	8298
	4327656	52976
Compressor Shaft Seal Kit-Sanden, Carbon Style	4338897 72162170	52552
Compressor-New Sanden SD508	4338042 7807944	8387
Condenser	86747 4341371	AC001009
Evaporator	4347538 4402838	N/A
Expansion Valve-Block Type	4322165 3311533M91	EX03700
Receiver Drier-O'Ring, Replaces Early Style RD03349, Requires Some Modification	4346256 4353731 70276903	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349
Switch-Blower  Pressure Thermostat	4322169 4372360	71R1210
	4337855	71R7500
	4360486	26301
	4338212	
<b>DEUTZ DX3.30 TRACTOR</b>		
Blower Motor-Condenser Motor, 11" Universal Electric Fan Assembly Blower Motor	70276779	FA11235
	4378971	BA4080

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX3.30 TRACTOR Cont.</b>		
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove New Clutch Coil, Sanden	4327654	8298
	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897 72162170	52552
<b>Compressor</b> -New Sanden SD508	70276762	8387
<b>Condenser</b>	86747 4341371	AC001009
<b>Evaporator</b>	4347538 4402838	N/A
<b>Expansion Valve</b> -Block Type	4322165 3311533M91	EX03700
<b>Receiver Drier</b> -O'Ring O'Ring, Replaces Early Style RD03349, Requires Some Modification  O'Ring, Early Style	70276781	800-122
	4346256 4353731 70276903	26831
	4353731 70276903 4346256	RD03349
<b>Switch</b> -Blower  Pressure Thermostat	4322169 4372360	71R1210
	4337855	71R7500
	4360486 4338212	26301
<b>DEUTZ DX3.30VF TRACTOR</b>		
<b>Compressor</b> -Sanden SD508	70276762	8387
<b>Expansion Valve</b> -Block Type	71307202	EX03700
<b>Receiver Drier</b>	70276781	800-122
<b>DEUTZ DX3.50 TRACTOR</b>		
<b>Blower Motor</b> -Condenser Motor, 11" Universal Electric Fan Assembly Condenser Fan, with Relay and Wiring Harness Blower Motor	4322172	FA11235
	4322172	FA11235-1
	4348005	BA4080
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove New Clutch Coil, Sanden	4327654	8298
	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897 72162170	52552
<b>Compressor</b> -New Sanden SD508	4338042 7807944	8387
<b>Condenser</b>	86747 4341371	AC001009
<b>Evaporator</b>	4347538 4402838	N/A
<b>Expansion Valve</b> -Block Type	4322165 3311533M91	EX03700

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX3.50 TRACTOR Cont.</b>		
<b>Receiver Drier</b> -O'Ring, Replaces Early Style RD03349, Requires Some Modification	4346256 4353731 70276903	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349
<b>Switch-Blower</b>	4322169 4372360	71R1210
Pressure	4337855	71R7500
Thermostat	4360486 4338212	26301
<b>DEUTZ DX3.50VF TRACTOR</b>		
<b>Compressor</b> -Sanden SD508	70276762	8387
<b>Expansion Valve</b> -Block Type	71307202	EX03700
<b>Receiver Drier</b>	70276781	800-122
<b>DEUTZ DX3.70 TRACTOR</b>		
<b>Blower Motor</b> -Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
Blower Motor	4348005	BA4080
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897 72162170	52552
<b>Compressor</b> -New Sanden SD508	4363723	8387
<b>Condenser</b>	4341371	AC001009
<b>Evaporator</b>	4337049	N/A
<b>Expansion Valve</b> -Block Type	4322165	EX03700
<b>Receiver Drier</b> -O'Ring, Replaces Early Style RD03349, Requires Some Modification	4353731 70276903	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349
<b>Switch-Blower</b>	4322169 4372360	71R1210
Pressure	4337855	71R7500
Thermostat	4360486 4338212	26301
<b>DEUTZ DX3.90 TRACTOR</b>		
<b>Blower Motor</b> -Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
Blower Motor	4378971	BA4080
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897 72162170	52552

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX3.90 TRACTOR Cont.</b>		
Compressor-New Sanden SD508	7807944	8387
Condenser	4341371	AC001009
Evaporator	4347538 4402838	N/A
Expansion Valve-Block Type	71307202	EX03700
Receiver Drier-O'Ring, Replaces Early Style RD03349, Requires Some Modification	4346256 4353731 70276903	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349
Switch-Low Pressure	70276750	N/A
High Pressure	71190643	71R6070
High-Low Pressure	4337855	71R7500
Thermostat	70276733	26301
<b>DEUTZ DX4.70 TRACTOR</b>		
Blower Motor-Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
Blower Motor	4348005 4378971	BA4080
Clutch Bearing-Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
Clutch-New Sanden, 5.98" Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
Compressor Shaft Seal Kit-Sanden, Carbon Style	4338897 72162170	52552
Compressor-New Sanden SD508	4363723 7807944	8387
Condenser	86747 4341371	AC001009
Evaporator	4347538 4402838	N/A
Expansion Valve-Block Type	4322165 3311533M91	EX03700
Receiver Drier-O'Ring, Replaces Early Style RD03349, Requires Some Modification	70276903 43462556 4353731	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349
Switch-Low Pressure	70276750	N/A
High Pressure	71190643	71R6070
High-Low Pressure	4337855	71R7500
Thermostat	70276733	26301
<b>DEUTZ DX6.30 TRACTOR</b>		
Blower Motor-Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
Blower Motor	4348005 4378971	BA4080

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX6.30 TRACTOR Cont.</b>		
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove New Clutch Coil, Sanden	4327654	8298
	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897 72162170	52552
<b>Compressor</b> -New Sanden SD508	4363723 7807944	8387
<b>Condenser</b>	4321436 4337405	AC002325
<b>Evaporator</b>	4347538 4402838	N/A
<b>Expansion Valve</b> -Block Type	4322165 3311533M91	EX03700
<b>Receiver Drier</b> -O'Ring, Replaces Early Style RD03349, Requires Some Modification O'Ring, Early Style	70276903	26831
	4353731	RD03349
	70276903	
	4346256	
<b>Switch</b> -Low Pressure High Pressure High-Low Pressure Thermostat	70276750	N/A
	71190643	71R6070
	4337855	71R7500
	70276733 4338212	26301
<b>DEUTZ DX6.50 TRACTOR</b>		
<b>Blower Motor</b> -Condenser Motor, 11' Universal Electric Fan Assembly Condenser Fan, with Relay and Wiring Harness Blower Motor	4322172	FA11235
	4322172	FA11235-1
	4348005	BA4080
	4378971	
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove New Clutch Coil, Sanden	4327654	8298
	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897 72162170	52552
<b>Compressor</b> -New Sanden SD508	4363723 7807944	8387
<b>Condenser</b>	4321436 4337405	AC002325
<b>Evaporator</b>	4347538 4402838	N/A
<b>Expansion Valve</b> -Block Type	4322165 3311533M91	EX03700
<b>Receiver Drier</b> -O'Ring, Replaces Early Style RD03349, Requires Some Modification O'Ring, Early Style	4346256	26831
	4353731	
	70276903	
	4353731 70276903 4346256	RD03349

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX6.50 TRACTOR Cont.</b>		
Switch-Low Pressure	70276750	N/A
High Pressure	71190643	71R6070
High-Low Pressure	4337855	71R7500
Thermostat	4338212	26301
	70226733	
<b>DEUTZ DX7.10 TRACTOR</b>		
<b>Blower Motor</b> -Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
Blower Motor	4348005	BA4080
	4338971	
<b>Clutch</b> -New Sanden, 5.98 Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897	52552
	72162170	
<b>Compressor</b> -New Sanden SD508	4363723	8387
	7807944	
<b>Condenser</b>	4321436	AC002325
	4337405	
<b>Evaporator</b>	4347538	N/A
	4402838	
<b>Expansion Valve</b> -Block Type	4322165	EX03700
	3311533M91	
<b>Receiver Drier</b> -O'Ring, Replaces Early Style RD03349, Requires Some Modification	4346256	26831
	4353731	
	70276903	
O'Ring, Early Style	4353731	RD03349
	70276903	
	4346256	
Switch-Low Pressure	70276750	N/A
High Pressure	71190643	71R6070
High-Low Pressure	4337855	71R7500
Thermostat	70276733	26301
<b>DEUTZ DX8.30 TRACTOR</b>		
<b>Blower Motor</b> -5/16" Double Shaft (Must Use Original Wheels) Dash Mount	4317577	BA4070
	4339305	
Replacement Motor For BA4070	N/A	BM4071
Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW	N/A	BW270
Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW	N/A	BW271
Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
<b>Clutch Bearing</b> -A6	702575700	12589
Dust Protector, A6, 2 Piece Clutch Bearing Dust Seal	N/A	47251
<b>Clutch</b> -Clutch Hub Dust Cover, A6, Plastic Dust Cover w/o Screws	N/A	12440
New Clutch Hub, A6	4330738	12197
New Clutch w/o Coil, A6	4330737	8088
	4330738	
New Clutch Coil, A6	4330739	12417

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX8.30 TRACTOR Cont.</b>		
<b>Compressor Shaft Seal Kit-A6, w/Steel Wear Plate</b> A6, w/ Ceramic Wear Plate	4331451	20939
	4331451	20938
<b>Compressor-Reman A6, New Clutch, No Oil</b>	4343180	04005
<b>Condenser</b>	4325867	N/A
<b>Evaporator</b>	4322161	N/A
<b>Expansion Valve-Block Type</b>	4322165	EX03700
<b>Receiver Drier-Flare</b>	4322166	803-307
<b>Switch-Thermostat</b> Blower  Bimetal Temperature	4325377	26301
	4322169 4372360	71R1210
	4322167	26506
<b>DEUTZ DX90 TRACTOR</b>		
<b>Blower Motor-5/16" Double Shaft (Must Use Original Wheels) Dash Mount</b>  Replacement Motor For BA4070 Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW Assembly, Roof Mount Condenser Motor, 11" Universal Electric Fan Assembly Condenser Fan, with Relay and Wiring Harness	4317577 4339305	BA4070
	N/A	BM4071
	N/A	BW270
	N/A	BW271
	4322159	BA4068
	4322172	FA11235
	4322172	FA11235-1
<b>Clutch Bearing-Sanden, For SD508, SD510, SD5H14 Compressor Only</b>	4327655	52560
<b>Clutch-New Sanden, 5.98" Dia., 2 Groove</b> New Clutch Coil, Sanden	4327654	8298
	4327656	52976
<b>Compressor Shaft Seal Kit-Sanden, Carbon Style</b>	4327658	52552
<b>Compressor-New Sanden SD508</b>	4330274	8387
<b>Condenser</b>	4321436 4337405	AC002325
	4322161	N/A
<b>Evaporator</b>	4322161	N/A
<b>Expansion Valve-Block Type</b>	4322165	EX03700
<b>Receiver Drier-Flare, 76 Series Tractors</b> O'Ring, Replaces Early Style Drier RD03349, Requires Some Modification  O'Ring, Early Style	4322166	803-307
	4346256 7027903	26831
	4353731 70276903 4346256	RD03349
<b>Switch-Bimetal Temperature</b> Blower  Thermostat	4322167	26506
	4322169 4372360	71R1210
	4325377	26301

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX92 TRACTOR</b>		
<b>Blower Motor</b> -5/16" Double Shaft (Must Use Original Wheels) Dash Mount	4317577 4339305	BA4070
Replacement Motor For BA4070	N/A	BM4071
Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW	N/A	BW270
Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW	N/A	BW271
Assembly, Roof Mount	4322159	BA4068
Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4338894 4363718	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	4338893	8298
New Clutch Coil, Sanden	4338896	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4338897 72162170	52552
<b>Compressor</b> -New Sanden SD508	4338042 7807944	8387
<b>Condenser</b>	4341371	AC001009
<b>Evaporator</b>	4347538 4402838	N/A
<b>Expansion Valve</b> -Block Type	4322165 3311533M91	EX03700
<b>Receiver Drier</b> -O'Ring, Replaces Early Style Drier RD03349, Requires Some Modification	4346256 70276903	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349
<b>Switch</b> -Blower	4322169 4372360	71R1210
Pressure	4337855 4363011	71R7500
Thermostat	4338212 4360486	26301
<b>DEUTZ DX110 TRACTOR</b>		
<b>Blower Motor</b> -5/16" Double Shaft (Must Use Original Wheels) Dash Mount	4317577 4339305	BA4070
Replacement Motor For BA4070	N/A	BM4071
Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW	N/A	BW270
Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW	N/A	BW271
Assembly, Roof Mount	4322159	BA4068
Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4327655	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4327658	52552
<b>Compressor</b> -New Sanden SD508	4330274	8387
<b>Condenser</b>	4321436 4337405	AC002325
<b>Evaporator</b>	4322161	N/A

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX110 TRACTOR Cont.</b>		
<b>Expansion Valve-Block Type</b>	4322165	EX03700
<b>Receiver Drier-Flare, 76 Series Tractors</b> O'Ring, Replaces Early Style Drier RD03349, Requires Some Modification  O'Ring, Early Style	4322166	803-307
	4346256 70276903	26831
	4353731 70276903 4346256	RD03349
<b>Switch-Blower</b>  Bimetal Temperature Thermostat	4322169 4372360	71R1210
	4322167	26506
	4325377	26301
<b>DEUTZ DX120 TRACTOR</b>		
<b>Blower Motor-5/16" Double Shaft (Must Use Original Wheels) Dash Mount</b>  Replacement Motor For BA4070 Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW Assembly, Roof Mount Condenser Motor, 11" Universal Electric Fan Assembly Condenser Fan, with Relay and Wiring Harness	4317577 4339305	BA4070
	N/A	BM4071
	N/A	BW270
	N/A	BW271
	4322159	BA4068
	4322172	FA11235
	4322172	FA11235-1
<b>Clutch Bearing-Sanden, For SD508, SD510, SD5H14 Compressor Only</b>	4327655	52560
<b>Clutch-New Sanden, 5.98" Dia., 2 Groove</b> New Clutch Coil, Sanden	4327654	8298
	4327656	52976
<b>Compressor Shaft Seal Kit-Sanden, Carbon Style</b>	4327658	52552
<b>Compressor-New Sanden SD508</b>	4330274	8387
<b>Condenser</b>	4321436	AC002325
	4337405	
<b>Evaporator</b>	4322161	N/A
<b>Expansion Valve-Block Type</b>	4322165	EX03700
<b>Receiver Drier-Flare, 76 Series Tractors</b> O'Ring, Replaces Early Style Drier RD03349, Requires Some Modification  O'Ring, Early Style	4322166	803-307
	4346256 70276903	26831
	4353731 70276903 4346256	RD03349
<b>Switch-Blower</b>  Bimetal Temperature Thermostat	4322169 4372360	71R1210
	4322167	26506
	4325377	26301
<b>DEUTZ DX130 TRACTOR</b>		
<b>Blower Motor-5/16" Double Shaft (Must Use Original Wheels) Dash Mount</b>  Replacement Motor For BA4070 Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW Assembly, Roof Mount Condenser Motor, 11" Universal Electric Fan Assembly Condenser Fan, with Relay and Wiring Harness	4317577 4339305	BA4070
	N/A	BM4071
	N/A	BW270
	N/A	BW271
	4322159	BA4068
	4322172	FA11235
	4322172	FA11235-1

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX130 TRACTOR Cont.</b>		
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4327655	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove New Clutch Coil, Sanden	4327654	8298
	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4327658	52552
<b>Compressor</b> -New Sanden SD508	4330274	8387
<b>Condenser</b>	4321436 43337405	AC002325
<b>Evaporator</b>	4322161	N/A
<b>Expansion Valve</b> -Block Type	4322165	EX03700
<b>Receiver Drier</b> -Flare, 76 Series Tractors O'Ring, Replaces Early Style Drier RD03349, Requires Some Modification  O'Ring, Early Style	4322166	803-307
	4346256 70276903	26831
	4353731 70276903 4346256	RD03349
<b>Switch</b> -Blower  Bimetal Temperature Thermostat	4322169 4372360	71R1210
	4322167	26506
	4325377	26301
<b>DEUTZ DX140-160 TRACTOR</b>		
<b>Blower Motor</b> -5/16" Double Shaft (Must Use Original Wheels) Dash Mount  Replacement Motor For BA4070 Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW Assembly, Roof Mount Condenser Motor, 11" Universal Electric Fan Assembly Condenser Fan, with Relay and Wiring Harness	4317577 4339305	BA4070
	N/A	BM4071
	N/A	BW270
	N/A	BW271
	4322159	BA4068
	4322172	FA11235
	4322172	FA11235-1
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4327655	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove New Clutch Coil, Sanden	4327654	8298
	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4327658	52552
<b>Compressor</b> -New Sanden SD508	4330274	8387
<b>Condenser</b>	4321436 4337405	AC002325
<b>Evaporator</b>	4322161	N/A
<b>Expansion Valve</b> -Block Type	4322165	EX03700
<b>Receiver Drier</b> -Flare	4322166	803-307
<b>Switch</b> -Bimetal Temperature Blower  Blower, 76 Series Tractor Thermostat	4322167	26506
	4322169 4372360	71R1210
	N/A	71R1150
	4325377	26301

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX145 TRACTOR</b>		
<b>Blower Motor</b> -5/16" Double Shaft (Must Use Original Wheels) Dash Mount	4317577 4339305	BA4070
Replacement Motor For BA4070	N/A	BM4071
Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW	N/A	BW270
Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW	N/A	BW271
Assembly, Roof Mount	4322159	BA4068
Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
<b>Clutch Bearing</b> -Sanden, For SD508, SD510, SD5H14 Compressor Only	4327655	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4327658	52552
<b>Compressor</b> -New Sanden SD508	4330274	8387
<b>Condenser</b>	4321436 4337405	AC002325
<b>Evaporator</b>	4322161	N/A
<b>Expansion Valve</b> -Block Type	4322165	EX03700
<b>Receiver Drier</b> -Flare, 76 Series Tractors	4322166	803-307
O'Ring, Replaces Early Style Drier RD03349, Requires Some Modification	4346256 70276903	26831
O'Ring, Early Style	4353731 70276903 4346256	RD03349
<b>Switch</b> -Blower	4322169 4372360	71R1210
Bimetal Temperature	4322167	26506
Thermostat	4325377	26301
<b>DEUTZ DX160 TRACTOR</b>		
<b>Blower Motor</b> -5/16" Double Shaft (Must Use Original Wheels) Dash Mount	4317577 4339305	BA4070
Replacement Motor For BA4070	N/A	BM4071
Replacement Blower Wheel For BA4070, 4 1/8" Dia., CW	N/A	BW270
Replacement Blower Wheel for BA4070, 4 1/8" Dia., CCW	N/A	BW271
Assembly, Roof Mount	4322159	BA4068
Condenser Motor, 11" Universal Electric Fan Assembly	4322172	FA11235
Condenser Fan, with Relay and Wiring Harness	4322172	FA11235-1
<b>Clutch Bearing</b> -Sanden SD508, 510	4327655	52560
<b>Clutch</b> -New Sanden, 5.98" Dia., 2 Groove	4327654	8298
New Clutch Coil, Sanden	4327656	52976
<b>Compressor Shaft Seal Kit</b> -Sanden, Carbon Style	4327658	52552
<b>Compressor</b> -New Sanden SD508	4330274	8387
<b>Condenser</b>	4321436 4337405	AC002325
<b>Evaporator</b>	4322161	N/A
<b>Expansion Valve</b> -Block Type	4322165	EX03700
<b>Receiver Drier</b> -Flare	4322166	803-307

<b>DEUTZ TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>DEUTZ DX160 TRACTOR Cont.</b>		
Switch-Bimetal Temperature	4322167	26506
Blower	4322169 4372360	71R1210
Blower, 76 Series Tractor	N/A	71R1150
Thermostat	4325377	26301
<b>DEUTZ 6250VF TRACTOR</b>		
Compressor-New Sanden SD508	70276762	8387
Expansion Valve-Block Type	71307202	EX03700
Receiver Drier-O'Ring	70276781	RD00122
Switch-High Pressure, (NO, Metric Thread, Opens 275 PSI, Closes 330 PSI)	71190643 72506492	26512
High Pressure, (NC, Standard Thread, Closes 225 PSI, Open 375 PSI)	71190643 72506492	71R6070
<b>DEUTZ 6260FV TRACTOR</b>		
Compressor-New Sanden SD508	70276762	8387
Expansion Valve-Block Type	71307202	EX03700
Receiver Drier-O'Ring	70276781	RD00122
Switch-High Pressure, (NO, Metric Thread, Opens 275 PSI, Closes 330 PSI)	71190643 72506492	26512
High Pressure, (NC, Standard Thread, Closes 225 PSI, Open 375 PSI)	71190643 72506492	71R6070
<b>DEUTZ 6275F TRACTOR</b>		
Compressor-New Sanden SD508	70276762	8387
Expansion Valve-Block Type	71307202	EX03700
Receiver Drier-O'Ring	70276781	RD00122
Switch-High Pressure, (NO, Metric Thread, Opens 275 PSI, Closes 330 PSI)	71190643 72506492	26512
High Pressure, (NC, Standard Thread, Closes 225 PSI, Open 375 PSI)	71190643 72506492	71R6070